

ENERGY SAVED AT STORMWATER PUMP STATION WITH WASTOP IN SWEDEN

Location: Stockholm, Sweden
Customer: Stockholm Water

PROBLEM:

One of Stockholm's oldest storm water pump stations which lifted water a few meters was built with two metal flap valves. The flap valves didn't function particularly well and when the pump was not running water leaked back into the pump causing damage to the pump. This led to high repair costs and the pump ran more than necessary leading to higher energy usage. Noise pollution was another issue as every time the pump stopped the metal flap valves slammed shut causing irritation to local residents.



Stockholm WaStop



Stockholm WaStop

SOLUTION:

Wapro offered a WaStop NPS 30" as a solution. The existing opening and flange was measured and a customized WaStop was built to suit the pre-existing conditions. The WaStop was shorter than standard and the flange was placed in the middle of the valve to allow installation without any alterations to the existing building.

The WaStop valve has now been in operation since 2006 and hasn't required any repairs. It seals 100% and makes no noise when closing. WaStop valves have 16 feet. It was a perfect solution for this location with multiple problems.